RIX'S CREEK MINE DEPOSITION DUST GAUGE MONITORING 2022 RESULTS



WE CARE. WE DELIVER.

License Number: 3391 Licensee: RIXS CREEK PTY. LIMITED PO BOX 4 EAST MATLAND NSW 2323 Premises: RIXS CREEK COLLERY RIXS CREEK LANE SINGLETON NSW 2330
 Monitoring Frequency:
 Once a month

 Sampling Method:
 AM-19

 Limits:
 4 g/m³/month EPA Guideline

Pollutant: Units of measure:

re: g/m²/month

	Published: Sampled: Obtained:	1 February 2022 13 January 2022 25 January 2022	1 March 2022 4 February 2022 25 February 2022	1 April 2022 14 March 2022 28 March 2022	2 May 2022 14 April 2022 29 April 2022	1 June 2022 12 May 2022 23 May 2022	1 July 2022 9 June 2022 23 June 2022	
Sampling Point	Monitoring Location	JANUARY	FEBRUARY	MARCH	APRIL	MAY	JUNE	
25	D28	1.0	2.9	1.0	1.4	0.8	1.7	
29	D32	1.0	1.9	0.5	0.9	0.7	1.5	
1	Mean	1.0	2.4	0.8	1.2	0.8	1.6	
	Minimum	1.0	1.9	0.5	0.9	0.7	1.5	
	Maximum	1.0	2.9	1.0	1.4	0.8	1.7	

	Published: Sampled: Obtained:	1 August 2022 11 July 2022 21 July 2022	1 September 2022 11 August 2022 23 August 2022	3 October 2022 9 September 2022 20 September 2022	1 November 2022 11 October 2022 24 October 2022	9 December 2022 11 November 2022 24 November 2022	9 January 2023 12 December 2022 28 December 2022		
Sampling Point	Monitoring Location	JULY	AUGUST	SEPTEMBER	OCTOBER	NOVEMBER	DECEMBER	Year-to-date Average	EPA Guideline
25	D28	1.8	1.8	1.6	1.0	1.3	1.9	1.5	4
29	D32	1.7	1.7	1.5	5.3 *c	1.4	2.8	1.4	4
ſ	Mean	1.8	1.8	1.6	1.0	1.4	2.4		
	Minimum	1.7	1.7	1.5	1.0	1.3	1.9		
	Maximum	1.8	1.8	1.6	1.0	1.4	2.8		
	*c	*c - contaminated sample **d - damaged gauge (no result)							



