## **BLOOMFIELD COLLIERY**

## COMPLAINTS REGISTER



2023

| 8:40 pm noise from open cut on 24/10/23. Complainant said that noise sounded like rocks being dropped into empty dump truck. Explained that around th | No.   | About * | Time/Date | Location | Details | Action Taken / Findings   |
|---|-------|---------|-----------|----------|---------|---|
| likely noise source. The noise model indicated noise<br>enhancement to the east of the workings which does  | 23_01 | N       |           | Buttai   | •       | void. The temporary stockpile is located in a high position. Combined with an easterly wind, this was the |

\* D = Dust, N = Noise, B = Blasting, V = Visual, L = Lighting, W = Weeds, O = Other